

Prešov, 15 Nov. 2024

Product: Plate processors

## Warning Lamp kit to GNUC II Plate Processors

### Valid for following product(s):

For all Plate processor with a GNUC II control system.

### Issue(s)/symptom(s):

After updating our processor platforms with a new Android tablet MMI solution, we can now offer a warning light kit. The kit can also be purchased together with a new processor.

### Improvement(s):

The new Warning Light Kit provides signal light to display the ready/error state of the processor, further it provides a sound buzzer if the processor in an error stage.

Introduced are two Kits

#### 1) KIT,WARNING,LIGHT,With a new LDM board - 10115586 (instruction 10114858)

For processors with a production date before October 2024 (up 03/ 2024). Here it will be necessary to exchange the PCB LDM board.

Index	Ordering Code	Specification	10114857	10115586
1	10114779	SA,SIGNAL,LIGHT	1	1
2	10113269	CABLE,LAMP,STACKABLE,INDICATOR	1	1
3	10114783	SA,PLATE,SIGNAL,TOWER	1	1
4	10114858	INSTRUCTION,WARNING,LIGHT,MOUNTING (this instruction)	1	1
5	10061313	PCB GNUC LDM	0	1



Glunz & Jensen A/S (Headquarter)  
Selandia Park 1  
4100 Ringsted, Denmark  
Tel. +45 57 68 81 81  
[callcenter@glunz-jensen.com](mailto:callcenter@glunz-jensen.com)  
[www.glunz-jensen.com](http://www.glunz-jensen.com)

Glunz & Jensen, Inc. 2185 Hwy. 292  
Inman, SC 23349, USA  
Tel. +1 864 568 4638  
[callcenter@glunz-jensen.com](mailto:callcenter@glunz-jensen.com)  
[www.glunz-jensen.com](http://www.glunz-jensen.com)

Glunz & Jensen s.r.o.  
Kosická, 50  
08001 Prešov, Slovakia  
Tel. +421 51 7563811  
[callcenter@glunz-jensen.com](mailto:callcenter@glunz-jensen.com)  
[www.glunz-jensen.com](http://www.glunz-jensen.com)



## 2) KIT,WARNING,LIGHT – 10114857 (instruction 10114858)

For processors with production date from October 2024 (04/2024 and later). Here it **will not** be necessary to exchange the PCB LDM board. This kit does not contains a new PCB LDM board.

Index	Ordering Code	Specification	10114857	10115586
1	10114779	SA,SIGNAL,LIGHT	1	1
2	10113269	CABLE,LAMP,STACKABLE,INDICATOR	1	1
3	10114783	SA,PLATE,SIGNAL,TOWER	1	1
4	10114858	INSTRUCTION,WARNING,LIGHT,MOUNTING (this instruction)	1	1

Both kits contain the same signal light equipped with magnets for easy mounting, with desired visibility, anywhere on the processors iron covers. The kit also contains an iron plate with double adhesive tape (3) in case the kit must be mounted on other material than iron.



Glunz & Jensen A/S (Headquarter)  
Selandia Park 1  
4100 Ringsted, Denmark  
Tel. +45 57 68 81 81  
[callcenter@glunz-jensen.com](mailto:callcenter@glunz-jensen.com)  
[www.glunz-jensen.com](http://www.glunz-jensen.com)

Glunz & Jensen, Inc. 2185 Hwy. 292  
Inman, SC 23349, USA  
Tel. +1 864 568 4638  
[callcenter@glunz-jensen.com](mailto:callcenter@glunz-jensen.com)  
[www.glunz-jensen.com](http://www.glunz-jensen.com)

Glunz & Jensen s.r.o.  
Kosicka, 50  
08001 Prešov, Slovakia  
Tel. +421 51 7563811  
[callcenter@glunz-jensen.com](mailto:callcenter@glunz-jensen.com)  
[www.glunz-jensen.com](http://www.glunz-jensen.com)